Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight — ***DHR Id#:*** **046-5058**

Resource Identification

Property Name(s): ..... Redd House, 13465 Old Suffolk Road {Current
Property Date: ..... ca 1836
Address(s): ..... 13465 Old Suffolk Rd. {Current}
County/Independent City: Isle Of Wight
City: .....
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR
Surrounding area: ..... Rural

National Register Eligibility Status
Property is Historic (50 years or older)

Property has been recommended Not Eligible for listing

Resource Description

Ownership Status: ..... Private
Acreage: 100.0

Primary Resource Exterior Component Description:

Component	Comp Type/Form	Material	Material Treatment
Foundation	Foundation - Solid	Brick	Foundation - American Bond
Porch	Porch - 2-story	Wood	Porch - Post, Square
Roof	Roof - Gable, Side	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	Structural System - Vinyl Siding
Windows	Windows - Double-hung	Wood	Windows - 6/6
Chimneys	Chimneys - Exterior side	Brick	Chimneys - Flemish Bond
Chimneys	Chimneys - Central interior	Brick	Chimneys - Common Bond

Site Description: ..... Mr. Redd and his wife own this house and the surrounding property, which is on approximately 100 acres of land. There are four houses on the adjacent properties that are either used as rentals or are occupied by Mr. Redd's sons. This is a working farm.

Secondary Resource Desc: There are nine outbuildings associated with this farm complex.

WUZIT Count:

No.	Wuzit Types	Historic?
1	House	Historic
2	Shed	Historic
1	Smoke/Meat House	Historic
2	Stable	Historic
1	Equipment Shed	Historic
1	Barn	Historic
2	Garage	Historic

NR Resource Count:

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight **DHR Id#: 046-5058**

Individual Resource Information

WUZIT: ..... Shed

Est. Date of Construction: .... 1900 ca {Owner}
Primary Resource? ..... No
Architectural Style: ..... Other
Interior Plan Type: .....
Accessed? ..... No
Number of Stories: 1.0
Condition: ..... Good
Threats to Resource: ..... Transportation Expansion

Description: Northwest of the house is a shed that features a shed roof(A).

WUZIT: ..... Stable

Est. Date of Construction: .... 1940 ca {Owner}
Primary Resource? ..... No
Architectural Style: ..... Other
Interior Plan Type: .....
Accessed? ..... No
Number of Stories: 1.0
Condition: ..... Good
Threats to Resource: ..... Transportation Expansion

Description: Northwest of the house is a shed (A), equipment shed, and stable (A). The equipment shed and stable (A) are constructed of metal with standing-seam metal roofs.

WUZIT: ..... Equipment Shed

Est. Date of Construction: .... 1940 ca
Primary Resource? ..... No
Architectural Style: ..... Other
Interior Plan Type: .....
Accessed? ..... No
Number of Stories: 1.0
Condition: ..... Good
Threats to Resource: ..... Transportation Expansion

Description: Northwest of the house is a shed (A), equipment shed, and stable (A). The equipment shed and stable (A) are constructed of metal with standing-seam metal roofs.

WUZIT: ..... Shed

Est. Date of Construction: .... 1940 ca {Owner}
Primary Resource? ..... No
Architectural Style: ..... Other
Interior Plan Type: .....
Accessed? ..... No
Number of Stories: 1.0
Condition: ..... Good
Threats to Resource: ..... Transportation Expansion

Description: North of the smokehouse is a barn, stable (B), and shed (B). The shed (B) features a metal exterior and a roof clad in standing-seam metal.

WUZIT: ..... Stable

Est. Date of Construction: .... 1900 ca {Owner}
Primary Resource? ..... No
Architectural Style: ..... Other
Interior Plan Type: .....
Accessed? ..... No
Number of Stories: 1.0
Condition: ..... Good
Threats to Resource: ..... Transportation Expansion

Description: North of the smokehouse is a barn, stable (B), and shed (B). The stable (B) features a metal exterior and a roof clad in standing-seam metal.

WUZIT: ..... Barn

Est. Date of Construction: .... 1900 ca {Owner}
Primary Resource? ..... No
Architectural Style: ..... Other
Interior Plan Type: .....
Accessed? ..... No
Number of Stories: 2.0
Condition: ..... Good
Threats to Resource: ..... Transportation Expansion

Description: North of the smokehouse is a barn, stable (B), and shed (B). The barn is a large weatherboard clad structure with a gabled roof covered in standing-seam metal.

WUZIT: ..... Smoke/Meat House

Est. Date of Construction: .... 1900 ca
Primary Resource? ..... No
Architectural Style: ..... Other
Interior Plan Type: .....
Accessed? ..... No
Number of Stories: 2.0
Condition: ..... Good
Threats to Resource: ..... Transportation Expansion

Description: To the north of the garages is a smoke house. The smokehouse is a two-story structure with one-story, shed-roofed additions flanking each side. The exterior is weatherboard and the gabled roof is covered in standing-seam metal.

WUZIT: ..... Garage

Est. Date of Construction: .... 1940 ca {Owner}
Primary Resource? ..... No
Architectural Style: ..... Other
Interior Plan Type: .....
Accessed? ..... No
Number of Stories: 1.0
Condition: ..... Good
Threats to Resource: ..... Transportation Expansion

Description: Garage B features an exterior covered in vinyl siding and a gabled roof clad in composition shingles.

WUZIT: ..... Garage

Est. Date of Construction: .... 1940 ca {Owner}
Primary Resource? ..... No
Architectural Style: ..... Other
Interior Plan Type: .....
Accessed? ..... No
Number of Stories: 2.0
Condition: ..... Good
Threats to Resource: ..... Transportation Expansion

Description: There are nine outbuildings and one silo associated with this house. Northeast of the house are two garages (A&B). Garage A features a weatherboard exterior and a gabled roof covered in standing-seam metal.

WUZIT: ..... House

Est. Date of Construction: .... 1836 ca {Owner}
Primary Resource? ..... Yes
Architectural Style: ..... Other
Interior Plan Type: .....
Accessed? ..... No
Number of Stories: 2.0
Condition: ..... Good
Threats to Resource: ..... Transportation Expansion

Description: Built in 1836, this two-story I-House features a wooden frame structural system of hand-hewn 4x6 timbers that rests on brick piers with brick infill. The exterior of this house is covered in vinyl siding and the side-gabled roof is clad in standing-seam metal. A double-shouldered brick chimney is located on the east exterior end of the house and a second chimney is situated on the central interior portion of the one-story gabled addition on the north elevation. Another one-story gabled addition has been appended to the west façade. Fenestration consists of two-over-two and six-over-six wooden double-hung sash windows. The south elevation features a two-tier porch. The first floor porch features square wooden columns on brick piers and the second floor porch is screened. The porches were added to the house in the 1950s. The current owner Mr. Redd and his family have lived in the house since the 1950s. Mr. Redd is 83 years old and has lived within a mile of this house his entire life. His farm consists of approximately 100 acres of land.

Cemetery Information

Bridge Information

National Register Eligibility Information *(Intensive Level Survey)*

Historic Context(s): ..... Domestic
Subsistence/Agriculture

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-5058**

Historic Time Period(s): N- Antebellum Period (1830 to 1860)

Significance Statement: Though this house is currently in good condition, its design is common for the period of construction. This resource has no apparent association with any event or person important in our nation's history, lacks architectural significance, and does not appear to have the ability to yield important information. The architectural integrity of this house has been diminished due to numerous alterations including the addition of vinyl siding, some replacement windows, and multiple additions. The resource is recommended as not eligible for the NRHP under Criteria A, B, C, or D.

Bibliographic Documentation

Reference #: 1
Bibliographic RecordType: Survey
Author: CCR, Inc.
Citation Abbreviation:
Notes: VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

Ownership Information

Name: John and Martha Redd
Title:
Company:
Address:
City: Hanover
Zip: 23069 *State:* Virginia *Country:* USA
Phone/Extension:

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
35mm B&W	12	VDHR	2004/08/99	Farm Complex

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: Phase I Survey
Date: 2004/08/99
Organization or Person: CCR, Inc.
VDHR Project ID # Associated with Event: 2002-1760
CRM Event Notes or Comments: VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

CRM Event # 2,
Cultural Resource Management Event: DHR Staff: Not Eligible
Date: 2004/11/18
Organization or Person:
VDHR Project ID # Associated with Event: 2002-1760
CRM Event Notes or Comments: